



**ECS Southeast, LLP**

4984 BU Bowman Drive, Suite 201  
Buford, GA 30518  
6785468034  
6785468056

**LETTER OF TRANSMITTAL**

January 6, 2022

Unitarian Universalist Congregation of Atlanta  
1190 W Druid Hills Drive NE #150  
Atlanta, GA 30329  
ATTN: Mr. Bryce Thomason

RE: **Unitarian Universalist Congregation of Atlanta**  
ECS Job # **10:11013**  
Permits:  
Location: **2650 North Druid Hills Rd  
Atlanta, GA 30329**

Field Reports       For your use       As requested

CC: Choate Construction Company - Filiberto Lara  
Choate Construction Company - Greg Saborio

Choate Construction Company - Jeremiah Sutton  
Collins Cooper Carusi - Dawn Franklin  
Collins Cooper Carusi - Fiona Grandowski

ENCL: Field Report # 33      12/30/2021

Wesly Jacques, MSI  
Group Manager

Mario Leone  
Material Testing Staff Project Manager

*Disclaimer*

1. This report (and any attachments) shall not be reproduced except in full without prior written approval of ECS.
2. The information in this report relates only to the activities performed on the report date.
3. Where appropriate, this report includes statements as to compliance with applicable project drawings, and specifications for the activities, performed on this report date.
4. Incomplete or non-conforming work will be reported for future resolution.
5. The results of samples and/or specimens obtained or prepared for subsequent laboratory testing will be presented in separate reports/documents.



ECS Southeast, LLP  
 4984 BU Bowman Drive, Suite 201  
 Buford, GA 30518  
 (678) 546-8034 [Phone]  
 (678) 546-8056 [Fax]

## FIELD REPORT

Project **Unitarian Universalist Congregation of Atlanta**  
 Location **Atlanta, GA**  
 Client **Unitarian Universalist Congregation of Atlanta**  
 Contractor **None Listed**

Project No. **10:11013**  
 Report No. **33**  
 Day & Date **Thursday 12/30/2021**  
 Weather **60 °/ Rain**  
 On-Site Time **0.50**  
 Lab Time **0.25**  
 Travel Time\* **1.00**  
 Total **1.75**  
 Re Obs Time **0.00**

Remarks

Trip Charges*	<b>30.00</b>	Tolls/Parking*	Mileage*	Time of Arrival	Departure
Chargeable Items				<b>10:00A</b>	<b>10:30A</b>

\* Travel time and mileage will be billed in accordance with the contract.

<b>Summary of Services Performed (field test data, locations, elevations &amp; depths are estimates) &amp; Individuals Contacted.</b>
---

The undersigned arrived on site, as requested, to observe BMP's and to perform a weekly NPDES inspection.

Please see the attached NPDES Site Inspection Report for details.



**ECS SOUTHEAST, LLP**

4984 B U Bowman Dr #201  
 Buford, GA 30518

**NPDES SITE INSPECTION REPORT**

General Information			
<b>Project Name</b>	Unitarian Universalist Congregation of Atlanta		
<b>Client Name</b>	Unitarian Universalist Congregation of Atlanta		
<b>Project No.</b>	11013	<b>Work Order No.</b>	
<b>Date of Inspection</b>	12/30/2021	<b>Report No.</b>	
<b>Inspector's Name(s)</b>	Nakeita Watts		
<b>Type of Inspection</b>			
<input checked="" type="checkbox"/> Weekly <input type="checkbox"/> Daily <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
<b>Has rained since the last inspection?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
<b>If yes, provide:</b> Storm Start Date: 12/28/2021      Approximate Rainfall(in): 2.85			
<b>Weather at time of this inspection?</b>			
Rainy			

	BMP/Activity	Implemented?	Maintenance Required?	Corrective Action Needed and Notes
1	Are all disturbed areas not actively being worked properly stabilized or protected?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
3	Are perimeter controls and sediment barriers adequately installed and maintained?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Silt fence is damaged next to the construction entrance. Sediment trap needs to be place back at end of each work day.
4	Are storm drain inlets properly protected?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
5	Is there evidence of sediment being tracked into the street?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	



**ECS SOUTHEAST, LLP**

4984 B U Bowman Dr #201  
Buford, GA 30518

**NPDES SITE INSPECTION REPORT**

	<b>BMP/Activity</b>	<b>Implemented?</b>	<b>Maintenance Required?</b>	<b>Corrective Action Needed and Notes</b>
6	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	

**CERTIFICATION STATEMENT**

“ I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.”

Print Name: \_\_\_\_\_ Cert. #: \_\_\_\_\_

Signature: \_\_\_\_\_ Date: \_\_\_\_\_

The following was noted:

# Attachments



Silt fence ( maintenance is need to keep soil from going into public street)

Figure 1



Sediment trap ( needs a sediment trap to keep soil from going into public street)

Figure 2